








TS 2000 NV
TS 2000 NV BC









124953-04



GEZE





A $a \leq 1100 \text{ mm}$ **B** $a \leq 1100 \text{ mm}$ 

-  4x
-  5x70
-  4x
-  M5x55





4x
5x35
4x
M5x20





4x
M5x45



1





2




3



4



5




2x
5x20

2x
M5x16

6






10 mm




7





5 mm



a (mm) - EN





8





i+

TS 2000 NV BC



9



i

